US ERA ARCHIVE DOCUMENT

DECONTAMINATION/STAGING SITE ASSESSMENT

Facility Name :	Cocodrie	Facility Location ID:		on ID:	CocW01
Assessment Date :	8/6/2010	Incident Name :		:	BP Spill
Physical Location :	Cocodrie Marina 106 Pier 56				
City, State :	Chauvin, LA		County:	Terrebone	

ASSESSMENT INFORMATION

General Site Information and Observations					
1. All waste stored in lined rolloff boxes?	✓ Yes No N/A				
2. Rolloff boxes covered after filled (or end of day)?	Yes No N/A				
3. Any evidence of oily waste or oily waste waters?	Yes No N/A				
4. If yes, was it adequately addressed?	Yes No N/A				
5. How many samples were collected?					

Additional Comments:

There are 2 rolloffs and one intermodal container with oily wasate ready for offsite disposal. Two to Four rolloffs are shipped off site daily. There are two frac tanks on site one with approximately 1060 gallons of decon water. The other with approximately 8500 gallons of skimmer water/oil. Solid wastes were actively unloaded into rolloffs. EPA/ER TV video and photo documented activities on site.